

UNCLASSIFIED

AD NUMBER

AD107757

CLASSIFICATION CHANGES

TO: UNCLASSIFIED

FROM: CONFIDENTIAL

LIMITATION CHANGES

TO:

Approved for public release; distribution is
unlimited.

FROM:

Distribution authorized to U.S. Gov't. agencies
and their contractors;
Administrative/Operational Use; 13 MAY 1954.
Other requests shall be referred to Development
and Proof Services, Aberdeen Proving Ground,
MD.

AUTHORITY

APG ltr 19 Nov 1990 ; APG ltr 19 Nov 1990

THIS PAGE IS UNCLASSIFIED

AD- 107757

SECURITY REMARKING REQUIREMENTS

DOD 5200.1-R, DEC 78

REVIEW ON 13 MAY 74

UNCLASSIFIED

AD 107757

CLASSIFICATION CHANGED
TO: UNCLASSIFIED
FROM: CONFIDENTIAL
AUTHORITY:

APG DA

1tr, 19 Nov 80



UNCLASSIFIED

CONFIDENTIAL

*Reproduced
by the*

ARMED SERVICES TECHNICAL INFORMATION AGENCY
ARLINGTON HALL STATION
ARLINGTON 12, VIRGINIA



DECLASSIFIED AFTER 12 YEARS
DOD DIR 5200.10

CONFIDENTIAL

CONFIDENTIAL
A107757

Armed Services Technical Information Agency

Reproduced by
DOCUMENT SERVICE CENTER
KNOTT BUILDING, DAYTON, 2, OHIO

This document is the property of the United States Government. It is furnished for the duration of the contract and shall be returned when no longer required, or upon recall by ASTIA to the following address: **Armed Services Technical Information Agency, Document Service Center, Knott Building, Dayton 2, Ohio.**


NOTICE: WHEN GOVERNMENT OR OTHER DRAWINGS, SPECIFICATIONS OR OTHER DATA ARE USED FOR ANY PURPOSE OTHER THAN IN CONNECTION WITH A DEFINITELY RELATED GOVERNMENT PROCUREMENT OPERATION, THE U. S. GOVERNMENT THEREBY INCURS NO RESPONSIBILITY, NOR ANY OBLIGATION WHATSOEVER; AND THE FACT THAT THE GOVERNMENT MAY HAVE FORMULATED, FURNISHED, OR IN ANY WAY SUPPLIED THE SAID DRAWINGS, SPECIFICATIONS, OR OTHER DATA IS NOT TO BE REGARDED BY IMPLICATION OR OTHERWISE AS IN ANY MANNER LICENSING THE HOLDER OR ANY OTHER PERSON OR CORPORATION, OR CONVEYING ANY RIGHTS OR PERMISSION TO MANUFACTURE, USE OR SELL ANY PATENTED INVENTION THAT MAY IN ANY WAY BE RELATED THERETO.

CONFIDENTIAL

NOTICE: THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE
NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING
OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 and 794.
THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN
ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

AD NO. 107757

RTMA FILE COPY



CONFIDENTIAL

CONFIDENTIAL

A TEST COMPARING THE 105MM CARTRIDGE, T119E12 AND THE
105MM CARTRIDGE, T184E13 UNDER WINTER ARCTIC CONDITIONS

FIRST REPORT ON PROJECT NO. TAI-1536

143RD REPORT ON PROJECT NO. TB5-1401

THIS DOCUMENT CONSISTS OF 91 PAGES
COPY 1 OF ... 23 ... COPIES, SERIES

RETAIN OR DESTROY PER AR 380-5 AND
SR345-215-5 OR COMPARABLE AF OR NAVY
REGULATIONS. DO NOT RETURN

JUN 22 1955

55

26649

CONFIDENTIAL
CONFIDENTIAL

CLIMATIC TEST DIVISION
ABERDEEN PROVING GROUND,
MARYLAND

Mr Engelhardt/mp/5233
13 May 1954

Authority : ORDN

DA Priority: 1A

A TEST COMPARING THE 105mm CARTRIDGE, T119E12
AND THE 105mm CARTRIDGE, T184E13 UNDER WINTER
ARCTIC CONDITIONS AT FORT CHURCHILL, MANITOBA,

CANADA.

FIRST REPORT ON PROJECT NO. TAL-1536

143RD REPORT ON PROJECT NO. TB5-1401

DATES OF TEST: 13 February to 22 February 1954

OBJECT

To compare the accuracy and ignition characteristics of the T119E12 and T184E13 rounds under winter arctic conditions.

SUMMARY

The two types of subject rounds were tested for accuracy at 1000 yards and 1500 yards at temperatures down to -26°F with satisfactory results. The T184E13 round was observed to have several material defects which could restrict its use at low temperatures.

CONCLUSIONS

It is concluded that the accuracy of the 105mm Cartridge, T119E12 is satisfactory at 1000 yards at temperatures down to -26°F . It is concluded that the accuracy of the 105mm Cartridge T184E13 is satisfactory at 1000 yards and 1500 yards at temperatures down to -20°F . The durability of the positioning ring and the liner on the T184E13 round is unsatisfactory.

RECOMMENDATIONS

It is recommended that the accuracy of the 105mm Cartridge, T119E12 be considered satisfactory at 1000 yards at temperatures down to -26°F and that the accuracy of the 105mm Cartridge, T184E13 be considered satisfactory at ranges of 1000 and 1500 yards at temperatures down to -20°F . It is recommended that improvements be made in the liner and positioning ring used on the T184E13 cartridge in order to enable them to withstand normal handling procedures at low temperatures.

DISTRIBUTION FOR FIRST REPORT ON PROJECT NO. TAL-1536

CONFIDENTIAL

AND 143RD REPORT ON PROJECT NO. TB-1401.

Final Report Distribution:

Copies

Chief of Ordnance
Washington 25, D. C.
Attn: ORDTB
ORDTA
ORDLR
ORDTS

1
1
1
1

Ordnance Ammunition Center
Joliet, Illinois
Attn: ORILY-I-A

1

Frankford Arsenal
Philadelphia, Pennsylvania
Attn: ORDBA-RE

1

Picatinny Arsenal
Dover, New Jersey
Attn: ORDBB-TE3

1

Climatic Test Division
Aberdeen Proving Ground, Maryland

1

Technical Information Branch
Aberdeen Proving Ground, Maryland

Original & 1 copy

Ordnance Climatic Test Detachment
Yuma Test Station, Yuma, Arizona

1

Southwest Research Institute
8500 Culebra Road
San Antonio 6, Texas

1

First Arctic Test Detachment
Fort Churchill, Manitoba, Canada

6

Armed Services Technical Information Agency
Document Service Center
Dayton, Ohio
Thru: T.I.B., APG, Md.

2

Liaison Officer
Aberdeen Proving Ground, Maryland
Attn: Army Field Forces
Thru: T.I.B., APG, Md.

2

DISTRIBUTION FOR FIRST REPORT ON PROJECT NO. TA1-1536

AND 143RD REPORT ON PROJECT NO. TB5-1401

<u>Final Report Distribution:</u>	<u>Copies</u>
Chief of Ordnance Department of the Army Washington 25, D. C. Attn: ORDIM ORDTX-AR	1 1

I. INTRODUCTIONA. DISCUSSION

Extensive tests have been conducted on both the T119E12 and the T184E13 rounds at Aberdeen Proving Ground with respect to accuracy. The majority of these tests have been conducted in the 70° temperature range and both rounds appeared to have satisfactory accuracy characteristics. It was desired to investigate these two rounds under winter arctic conditions in order to determine, if any, the effect of this particular type of environment on the velocity and stability of both types of rounds.

The T119E11 round differs from the T119E12 round in that the T119E12 round has a counterbore on the base end of the cartridge case to accomodate the breech on the M27 rifle. In previous tests at Aberdeen Proving Ground, it was discovered that the mechanism driving the fins outward on the T119E11 round would not function properly at -40°F. This resulted in a very erratic flight of the projectile. To combat this deficiency, the rounds were modified by increasing the clearance between the piston and the piston stop interference ring and reducing the shear ring cross-sectional area. This modified T119E12 round was the type used for the tests included in this report.

The T184 type round was originally developed for the 105mm, M27 rifle. However, in the early part of 1952, the T170 type rifle was developed which had the M27 tube and a smaller chamber similar to that of a previous rifle, the T136. When the T184 type projectiles first employing an end plate were used in the M27 rifle, they became known as the T184E5; in the T170 rifle, as the T184E6. Later both the M27 and the T170 rifles were counterbored at the origin of the rifling to permit the use of the T119 type of projectile. The T184 type rounds which were used in the counterbored M27 and T170 rifles became known as the T184E13 and the T184E12 respectively.

The T119 type round which has folding fins was developed by the Firestone Tire and Rubber Company for use in a smoothbore tube. The smoothbore tube was discarded and through successive modifications the round was developed for use in the counterbored M27 rifle and the counterbored T170 rifle which is designated as the T170E1 and is used in the BAT system. The round when used in the M27 rifle is known as the T119E12 and as the T119E11 when used in the T170E1 rifle.

B. REFERENCES

1. Authority for test (copy attached as appendix A)

a. Letter file 00 400.112/2772, APG 400.112/1496, dated 25 August 1953, Subject: "Proposed Ordnance Environmental Tests Winter 1953-54, Fort Churchill, Manitoba, Canada, and Flin Flon, Canada".

2. Technical References

a. Development and Proof Services Firing Record No. P55424

b. Progress Reports of Firestone Tire and Rubber Company on Battalion Anti-tank Project, Ordnance Department Project No. TAL-1540 (Ammunition), TSH-4020 (Weapons and Accessories)

CONFIDENTIAL

c. Frankford Arsenal Report - Status reports on Battalion Anti-tank Weapons and Ammunition, Project TS4-4020, TAl-1540, and TAl-1536.

II DESCRIPTION OF MATERIEL

A. 105mm CARTRIDGE, HEAT, T119E12

The Cartridge, HEAT, T119E12 is a non-rotated round which obtains its stability from six aluminum folding fins. Upon ignition, the fins are forced into their normal flight position by a piston operated by the propelling gases. This piston is located in the rear of the round and operated on a pressure differential basis which prevents actuation of the piston until the round has cleared the tube. The piston is held in its final position by a knurled interference ring which in turn keeps the fins in their flight position. This round employs a conventional crimp at the mouth of the cartridge case and uses a polyethylene and rayon liner. The propellant is placed in the round by means of a plug which screws into the base of the cartridge case.

B. 105mm CARTRIDGE, HEAT, T184E13

The 105mm cartridge, HEAT, T184E13 is also a non-rotated round which obtains its stability through the use of six fixed aluminum fins which have an outer diameter slightly less than the caliber diameter. These fins have an end plate and are connected to the projectile by means of a boom which also contains the ignition cartridge. The projectile is held to the case by the primer head which is screwed into a retainer attached to the case. The debulleting force is obtained by shearing the neck of the retainer. The round is held at the mouth of the case by a plastic positioning ring and it has an external nitrocellulose liner.

III DETAILS OF TEST

A. PROCEDURE

1. An accuracy pattern was fired at a 1000 yard and a 1500 yard range with each type of ammunition. The procedure used was similar to that described in the Ordnance Proof Manual for accuracy firing.

2. The complete program was fired with the weapon mounted on the truck, 1/4-ton, M38, with the gunner sitting in the truck beside the gun in his normal firing position. The stability of the mount on the snow covered terrain was excellent. All velocity measurements were made with sky screens placed approximately 100 and 140 feet from the muzzle respectively. The Potter counter chronograph and the sky screens used an M5 portable generator as a power source.

3. The ammunition was removed from the boxcar and placed on sleds. The sleds were then towed by a tracklaying vehicle to the firing position which was a distance of approximately 10 miles, 7 of which was over unprepared roads. The ammunition crates were then stacked in the open for a period ranging up to two weeks before firing. The weather conditions during this storage period may be found in Appendix D.

4. All ammunition was inspected before firing and appropriate observations were made.

CONFIDENTIAL

B. RESULTS

1. The results of the test are as follows:

	T119E12 1008 Yard Range	T119E12 1008 Yard Range	T184E13 1008 Yard Range	T184E13 1508 Yard Range
--	-------------------------------	-------------------------------	-------------------------------	-------------------------------

Number of rounds fired in accuracy pattern not including conditioning rounds.

16	16	18	15
----	----	----	----

Number of rounds which missed target in accuracy pattern not including conditioning rounds.

0	7	0	1
---	---	---	---

Probable Error*

.333	.456	.387	.573
------	------	------	------

Vertical (MILS)

.257	.305	.453	.401
------	------	------	------

Lateral (MILS)

Lost	1548	1519	1516
------	------	------	------

Average Velocity (FPS)

37	41	39	
----	----	----	--

Maximum Velocity Dispersion Between Rounds (FPS)

37	41	39	
----	----	----	--

*NOTE: These figures are not corrected for velocity.

2. No velocity data was obtained during the test of the T119E12 cartridge at the 1008 yard range because the skyscreens used for velocity measurements were not functioning properly.

3. Of the 40 rounds of T184E13 ammunition received for test, the liner was cracked on 11 of these rounds and had fallen away from the cartridge case on four rounds exposing 4 to 8 square inches of the perforations and allowing the propellant to spill out. Sixteen positioning rings were cracked and four (4) were shattered.

4. All of the T184E13 rounds produced a muzzle after burning flame of one half to two feet in length.

5. All cartridge cases and primers were in good condition after firing. All projectile flights appeared to be stable as observed through a BC scope. All ammunition with the exceptions mentioned in paragraph 3 above arrived in good condition.

6. Temperatures to which the rounds were subjected while in storage at the firing position may be found in Appendix D.

C. OBSERVATIONS

1. No shattered positioning rings were damaged to the point that they could no longer support the projectile. The cracked positioning rings were still intact with all pieces still in place whereas the shattered rings were observed to have pieces which had broken off and fallen into the fiber shipping container. See APG Photograph No. A96306, Appendix F.

CONFIDENTIAL

2. The cracked liners were still adhered to the case and no pieces had fallen off. Four rounds had a liner which had cracked and had fallen completely away from the case allowing the propellant to spill out of the case perforations; however, care was taken when the rounds were handled prior to firing and very little propellant was lost.

3. The faulty liners and positioning rings did not appear to affect the performance of the round. Special attention was given to these rounds in order to minimize the effect of the defective parts, but under field conditions, the poor durability of the liners and conditioning rings could affect the round performance.

4. The transportation of the ammunition on sleds for a distance of 10 miles subjected the rounds to considerable jolting and bumping which could have influenced the malfunctions of the T184E13 liners and positioning rings.

5. It was not possible to fire the accuracy groups at the same range on the same day as requested in the test plan because the conditions under which the tests were conducted slowed firing and preparation procedures considerably in comparison to tests conducted under temperate conditions.

6. The firing handle on the M27 rifle was somewhat small for use with the arctic mitt. The gunner reported that the tight fit within the firing handle had a tendency to move the gun off of the aiming point in the event the gun was sighted before the firing handle was grasped. See APG Photograph A96304, Appendix F.

7. The seven rounds which missed the target while firing the T119E12 round at a 1508 yard range tend to make the probable error figures questionable. For this reason, no conclusions have been made on this round at this range. The reason for seven rounds missing the target is not known. All rounds passed over the target and for that reason the elevation of the tube as well as the method for laying the weapon were very carefully checked after two rounds had passed over the target. No discrepancies were noted.

8. The use of sky screens for taking velocity data is extremely advantageous in the arctic. It eliminated the use of the magnetizer which required constant protection to prevent snow from shorting out the electrical circuit. It also eliminated the use of velocity coils which are difficult to manipulate while wearing arctic gear.

9. It was found that all ammunition handling procedures could be easily accomplished while the crew was wearing arctic clothing.

10. The muzzle after burning flame of the T184E13 round did not endanger or hamper the operation of the gunner.

IV. CONCLUSIONS

It is concluded that:

A. The accuracy of the 105mm Cartridge, HEAT, T119E12 is satisfactory at a range of 1000 yards at temperatures down to -26°F.

CONFIDENTIAL

CONFIDENTIAL

B. The accuracy of the 105mm Cartridge, HEAT, T184E13 is satisfactory at ranges of 1000 and 1500 yards at temperatures down to -20°F.

C. The velocity characteristics of both rounds are satisfactory down to temperatures of -20°F.

D. The durability of the liner and positioning ring used in the T184E13 cartridge is unsatisfactory when subjected to normal ammunition handling procedures at temperatures as low as -25°F.

V. RECOMMENDATIONS

It is recommended that:

A. The accuracy of the 105mm Cartridge, T119E12 be considered satisfactory at a 1000 yard range and temperatures down to -25°F.

B. The accuracy of the 105mm Cartridge, HEAT, T184E13 be considered satisfactory at ranges of 1000 and 1500 yards at temperatures down to -20°F.

C. A liner and positioning ring be developed for the T184E13 round that will withstand rough handling at low temperatures without failures.

CONFIDENTIAL

SUBMITTED BY:

B. S. Goodwin
B. S. GOODWIN
Chief, Arms & Ammunition Division
Development and Proof Services

PREPARED BY:

R. E. Engelhardt
R. E. ENGELHARDT
Project Engineer
Southwest Research Institute

APPROVED BY:

T. F. Collier
T. F. COLLERAN
Director
Development and Proof Services

REVIEWED BY:

A. B. Duke
A. B. DUKE
Lt Col, Ord Corps
Chief, Climatic Test Division
Development and Proof Services

CONFIDENTIAL

CONFIDENTIAL

APPENDICES

- A. CORRESPONDENCE
- B. TEST PLAN
- C. FIRING RECORD
- D. DATA REDUCTION ANALYSIS
- E. WEATHER DATA
- F. ENVANAL RATING CHART
- G. PHOTOGRAPH

10

11-60-47-12193

CONFIDENTIAL

CONFIDENTIAL

APPENDIX A

CORRESPONDENCE

1. Letter, file 00 400.112/2772, APG 400.112/1496
dated 25 August 1953.

||

ALL COMMUNICATIONS SHOULD BE ACCOMPANIED BY CARBON COPY AND ADDRESSED TO

EMSteward/es/56211

To Insure Prompt
Attention in Replying
Refer to:
OO 400.112/2772
APG 400.112/1496
ATTENTION OF:
ORDTB

WAR DEPARTMENT
OFFICE OF THE CHIEF OF ORDNANCE
WASHINGTON, D. C.

25 August 1953

SUBJECT: Proposed Ordnance Environmental Tests Winter 1953-54,
Fort Churchill, Manitoba, Canada, and Flin Flon, Canada

TO: Commanding General
Aberdeen Proving Ground
Maryland

Subject program has been approved by the Assistant Chief of
Staff, G-4.

BY COMMAND OF MAJOR GENERAL FORD:

/s/ N. L. KLEIN
Assistant

C O P Y

12

APPENDIX B
TEST PLAN

13

CONFIDENTIAL

CLIMATIC TEST DIVISION
DEVELOPMENT AND PROOF SERVICES
ABERDEEN PROVING GROUND
MARYLAND

TEST PLAN

Project: Winter Test Comparing 105mm Shell, T184E13 and 105mm Shell, T119E12 at Fort Churchill, Manitoba, Canada.

Project No.: 1st Report on Project TA1-1536
143rd Report on Project TB5-1401

Project Engineer: R. E. Engelhardt Priority: 1A

Authority: Letter dated 25 August 1953 00 400.112/2772, APG 400.112/1496

Object of Test:

To compare the accuracy and ignition characteristics of the subject rounds under arctic conditions.

Background:

The 184E13 cartridge has been standardized and is in production. It has had limited firing at -40°F and no resulting deficiencies have been noted.

The T119E12 cartridge is also in the limited production stage; however, recent firings at -40°F at Aberdeen Proving Ground with the T119E11 cartridge which is very similar to the T119E12, resulted in a malfunction in the mechanism which drives the fins outward. As a result of these tests, the clearance between the piston and the piston stop interference ring has been increased and the shear ring cross-sectional area has been reduced. The modified rounds have yet to be proof fired by Aberdeen Proving Ground but these changes are expected to correct any cold weather deficiencies of the round.

Description of Material:

The 105mm Shell, T184E13 is a HEAT round having six fixed fins with an end plate. The fins are connected to the projectile by means of a boom which also contains the ignition cartridge. The projectile is supported at the mouth of the case by a positioning ring.

The 105mm Shell, T119E12 is a HEAT round which has six folding fins. Upon ignition the fins are pushed into their normal flight position by a gas operated piston contained in the round. However, this piston operates on a pressure differential basis and is held in the original position until the round is free of the tube, thus preventing an attempt of the fins to open while the round is still in the tube. The only difference between this round and the 106mm Shell, T119E11, is a counterbore on the base end of the T119E12 cartridge case.

Detailed Test Procedure:

I. Positioning of Rifle

14

A. The rifle should be fired diagonally across the left side of the jeep, so that all adjustments may be made while standing on the ground.

B. Any cant in the system should be minimized by "digging in" the wheels of the jeep.

C. The M90C sight and the tube should be aligned on a common reference point on the target. A boresight case, and cross strings over the muzzle should be used. The sight must be cross-leveled during this operation. An allowance must be made for motion of the sight when tightening the locking nuts.

D. The quadrant should be positioned approximately at the center of the flat on the chamber. This position should be marked, and the quadrant returned to the same spot each time an adjustment is made. The boresight elevation (elevation when the line of sight through the bore coincides with the center of the target) should be measured and recorded. Since the reticle of the M90C sight is not graduated for the ammunition being tested, all elevations should be measured by the quadrant. They should be obtained by depressing rather than elevating the rifle.

E. The firing should be done remotely by a lanyard so attached that the rifle is not moved by the pull. This should be checked by "dry firing" several times while looking through the sight.

F. The velocity coils should be approximately 50 feet and 100 feet, respectively, from the muzzle. They must be so positioned that they do not obscure the target through the sight. Since the T119E12 projectile opens to approximately 11 inches in diameter, it must pass through the approximate center of each coil. The coil positions should be checked by sighting through the tube, and will probably have to be changed each time the deflection or elevation is changed. For this reason, it may be advisable, for the 1500 yard test, to fire one or two spotting rounds without taking velocities.

II. Aligning and Firing the Rifle

A. Load the rifle and close the breech.

B. Align the rifle laterally by means of the sight, and vertically by means of the quadrant. Always approach the lateral reference point by traversing in the same direction, and obtain the elevation by depressing the rifle. The cross-level bubble on the sight must be centered during this operation. The alignment should be checked carefully before leaving the rifle.

C. Attach the lanyard and fire remotely.

D. By means of the B. C. scope, observe the projectile in flight, and note the location of impact.

E. After firing, check the sight for alignment with the bore. If misalignment occurs, and the deficiency cannot be corrected, replace the sight or sight mount or both. Such a check should be made frequently during the test.

F. If necessary, make adjustments to relocate the center of impact by changing the elevation or using a different vertical reference line on the target.

CONFIDENTIAL

G. A group of approximately 15, T184E13 rounds and another group of approximately 15, T119E11 rounds should be fired at a 1000 yard target on the same day. Each round in a group should be fired at the same elevation and sight setting. Several rounds of one ammunition type will probably be needed as spotting rounds, which should not be included in the group, but whose location of impact should be measured. Using the other ammunition type for initial spotting, fire a group of each (total remaining rounds) at a 1500 yard target. Both the 1500 yard groups should be fired on the same day, which may be on a different day from the one of the 1000 yard firing. It is not advisable to attempt the 1500 yard firing if the wind velocity is over 10 mph and shifting. A steady wind may be compensated for.

III. Recording of Data and Observations

A. Record the boresight elevation, superelevation, and lateral deflection at which each round is fired. Suggested superelevations for the spotting rounds are as follows: T184E13, 23 mils for 1000 yards and 41 mils for 1500 yards; T119E12, 25 mils for 1000 yards and 44 mils for 1500 yards.

B. Record the average wind velocity during the flight of each projectile, muzzle velocity for each, and average temperature during the firing period.

C. Observe the projectile in flight through the B. C. scope, and note any evidence of instability. Examine the imprints on the target for evidence of yaw, and for fin opening of the T119E12 projectile. Measure the location of each impact in such a way that it may be related to the aiming point. Each impact should be identified in the order of firing. It is suggested that measurements be made from the center of the target, rounds above and to the right indicated as positive, and rounds below and to the left indicated as negative.

D. The range from the muzzle to the target should be measured to the closest yard. The coil distances should be measured to the closest .01 ft. (top and bottom distances averaged) and a temperature correction for the tape recorded.

IV. General

A. The ammunition should be stored without shelter, other than its own packaging, for whatever period of storage is required. The ammunition lot numbers, information on the weather conditions to which it has been subjected, including the range of temperature and relative humidity should be reported.

B. As the rounds are unpacked and fired, the general condition of the container and the ammunition should be noted and should include the following:

1. Ease of removal from the containers.
2. Condition of the moisture seal, and the positioning ring of the T184E13 round.
3. Ease with which the round is chambered, and the case extracted after firing. (Frequent light oiling of the breech will improve its functioning)
4. Condition of the cartridge case and primer after firing.

C. Should an erratic round be encountered during the test, every effort should be made to determine the cause, such as checking with the gunner for the possibility that the gun was not aligned properly, and examination of the area around the muzzle for evidence of projectile break-up.

D. The rifle should be observed for evidence of after-burning at the muzzle or breech, and accumulation of unburned propellant in the chamber.

E. In the event of a hang-fire or an obviously poor ignition, the sequence of events should be recorded as detailed as possible, i.e., the approximate time from the strike of the firing pin until the explosion, or the time of burning, the sound and the quantity, and color of smoke, should the propellant fail to explode.

F. In the event of a miss-fire the breech should be opened after a waiting period of 3 to 5 seconds. An attempt to fully close the breech after the trigger has been pulled may result in the rifle firing unexpectedly. The primer should be inspected to determine if it is too deeply seated in the case, and the rifle function fired. At least two more attempts to fire the round should be made. Miss-fires are quite frequently the fault of the weapon, and replacing the firing pin, or firing pin spring might eliminate the difficulty.

G. Care should be taken that the proper ammunition is used. The rounds for the 106mm rifle look almost exactly the same as the rounds for the 105mm rifle, and they could be fired from the 105mm rifle.

H. The accuracy of the groups should be expressed in terms of probable error in mils.

I. The general observations should include all aspects of the test and should be very detailed. These observations should be stated in the record even though many of them may appear to be of inconsequential importance.

J. Appropriate still and motion pictures will be taken of all phases of the test. Special attention will be given to all failures and unusual occurrences during the test.

K. An Envanal Chart will be completed at the end of the test and included in the formal report.

Instrumentation and Equipment Required:

Weapon, Mount, Sight, and Quadrant, mentioned under description of material, with spare sight and sight mount.

Plywood accuracy targets, 20 ft. square, marked off in three feet squares with lines that will be visible from the firing position, with timbers for bracing.

Thirty inch, velocity coils, with coil stands, wire and counter chronograph.

Anemometer, Thermometer, B. C. Scope

Spare parts for weapon such as sears, woodruff keys, firing pins, and firing pin springs.

Well equipped tool box, plus lanyard, boresight case, and squirt can of winter lubricating oil.

Ammunition Required:

40 ea., Cartridge, HEAT, Inert Projectile, T184EL3, 105mm Rifle, M27, Counter-bored.

40 ea., Cartridge, HEAT, Inert Projectile, T119EL2, 105mm Rifle, M27, Counter-bored.

Final Report Distribution:

Copies

Chief of Ordnance
Washington 25, D. C.
Attn: ORDTB
ORDTA
ORD IR
ORDTS

1
1
1
1

Ordnance Ammunition Center
Joliet, Illinois
Attn: ORDLY-I-A

1

Frankford Arsenal
Philadelphia, Pennsylvania
Attn: ORDBA-RE

1

Picatinny Arsenal
Dover, New Jersey
Attn: ORDBB-TE3

1

Climatic Test Division
Aberdeen Proving Ground, Maryland

1

Technical Information Branch
Aberdeen Proving Ground, Maryland

Original and 1 copy

Ordnance Climatic Test Detachment
Yuma Test Station, Yuma, Arizona

1

Southwest Research Institute
8500 Culebra Road
San Antonio 6, Texas

1

First Arctic Test Detachment
Fort Churchill, Manitoba, Canada

6

Armed Services Technical Information Agency
Document Service Center
Dayton, Ohio
Thru: T.I.B., APG, Md.

2

Liaison Officer
Aberdeen Proving Ground, Maryland
Attn: Army Field Forces
Thru: T.I.B., APG, Md.

2

References:

Firing Record No. PS5424
Progress reports of Firestone Tire and Rubber Company on Battalion Anti-Tank Project
Ordnance Department Project No. TAL-1540 (Ammunition), TS4-4020 (Weapon and
Accessories).
Frankford Arsenal Report, Status Reports on Battalion Anti-Tank Weapon and Ammunition
Projects TS4-4020, TAL-1540, TAL-1536

APPENDIX C

FIRING RECORD NO. P 58702

CLIMATIC TEST DIVISION
ABERDEEN PROVING GROUND, MARYLAND
FIRING RECORD

OBJECT OF TEST: To compare the accuracy and ignition characteristics of the Cartridge, HEAT, T119E12 and the Cartridge, HEAT, T184E13 under winter arctic conditions at Fort Churchill, Manitoba, Canada

DATE OF TEST: 13-22 February 1954
FIRING RECORD NO. P 58702
SHEET 1 OF
AUTHORITY: Letter dated 25 August 1953, OO 400.112/2772, APG 400.112/1496
WORK ORDER NO. 962-40-02-3

DEVELOPMENT: ORDTA

PROJECT NO: TB5-1401, TA1-1536

RELATED FIRING RECORDS: NONE

TEST AMMUNITION

CARTRIDGE, HEAT, Inert, T184E13 for 105mm Rifle, M27, Lot No. PA-E-14055 composed of the following components:

CASE, Cartridge, T48E2, Lot No. FA-E-1274

PRIMER, Percussion, T82, Lot No. PA-E-14042

FUZE, Dummy, T208E7

PROPELLANT, M10, MP. .031 Web, Charge Weight, 7.9 pounds
Lot No. PA-E-6101

IGNITION CARTRIDGE, (M50) T187, Boom, Lot No. PA-E-12667

IGNITION CARTRIDGE, (M49) T186, Tail, Lot No. PA-E-13126

CARTRIDGE ASSEMBLY, 105mm, T184E13, Lot No. FA-E-1605
Shell inert loaded with 70% PCN, 10% Celite, and
20% Iron Oxide

NITROCELLULOSE Liner

CARTRIDGE, HEAT, Inert, M343 (T119E12) with Fuze, Dummy, T208E7
for 105mm Rifle, M27, Lot No. PA-E-14178 composed of the following components:

CASE, Cartridge, T53E2, 105mm, Lot No. F4 lot 42

PRIMER, Percussion, M57, Lot No. LS-13-14

LINER ASSEMBLY, T4E1

FIN ASSEMBLY, T14

20

FIRING RECORD NO: P 58702
SHEET 2 OF

SHELL, 105mm, T119E12, inert loaded to 17.62 lbs. Lot No. 3

FUZE, Dummy, T208E7

PROPELLANT, M10, .031 web, charge weight 7 lbs. 12 ounces,
Lot No. PA-E-6101

MATERIEL

105MM, M27, Counterbored, Recoilless Rifle, No. 80 mounted on
Truck, 1/4 Ton, M38

MOUNT, Rifle, 105mm, M75, No. 45

TELESCOPE, M90D, No. 5570

MOUNT, Telescope, M3A1E1, No. 2

FACILITIES

Battery commander's telescope

Two Skyscreens

Counter Chronograph

M5 Generator

21

FIRING RECORD NO: P 58702
SHEET 3 OF

ROUND BY ROUND DATA

ACCURACY TEST, T119E12, 1008 YARD RANGE

WIND VELOCITY: 10 MPH

DATE: 13 February 1954

WIND DIRECTION: W

FIRING POSITION: D

TEMPERATURE: -26°F

DIRECTION OF FIRE: 310°F

BORESIGHT ELEVATION: 3 MILS

TEST SAMPLE NO.	TUBE ROUND NO.	TIME OF FIRING	IMPACT LAT FT.	COORDINATES VERT FT.	FIN SPREAD INS.	TOTAL ELEVATION MILS	REMARKS
C/R	237		8.2	2.3	10 $\frac{1}{2}$	25	
C/R	238			Low		25	
C/R	239		3.8	1.0	10 $\frac{1}{2}$	28	
C/R	240	1525		Low		28	
1	241		6.25	6.05	10-5/8	30	
2	242		3.6	3.65		30	
3	243		2.1	3.76	10-3/8	30	
4	244		5.75	6.95	10-5/8	30	
5	245		5.00	3.8		30	
6	246		4.1	5.35	10 $\frac{1}{2}$	30	
7	247		5.35	3.9		30	
8	248		6.7	5.3	10-3/8	30	
9	249		6.2	4.0	10-3/4	30	
10	250		4.9	2.85	10-7/8	30	
11	251		5.1	7.5	10-5/8	30	
12	252		4.9	5.2	10-5/8	30	
13	253		4.15	2.05	10-5/8	30	
14	254		4.3	3.8		30	
15	255		4.00	3.8		30	
16	256	1600	4.6	3.4		30	

REMARKS

1. All impact measurements made from left and bottom edges of 12' X 12' target.
2. All velocities were lost because of a malfunction of the skyscreens.
3. Gun was boresighted on left top corner of target.

22

FIRING RECORD NO: P 58702
SHEET 4 OF

ACCURACY TEST, T184E13 -1008 YARD RANGE

WIND VELOCITY: 6 MPH
WIND DIRECTION: NW
TEMPERATURE: -19°F

DATE: 14 February 1954
FIRING POSITION: D
DIRECTION OF FIRE: 310°
BORESIGHT ELEVATION: 3 MILS

TEST SAMPLE NO	TUBE ROUND NO	TIME OF FIRING	IMPACT LAT INS	COORDI- NATE VERT INS	MUZZLE VELOCITY FPS	MUZZLE BURNING LGTH FEET	POSITION- ING RING CONDI- TION	LINER CONDI- TION	REMARKS
----------------------	---------------------	----------------------	----------------------	--------------------------------	---------------------------	-----------------------------------	--	-------------------------	---------

C/R	257	1435	39	66.5	1541	1	C	C	
C/R	258		38	82	1521	1	C		
1	259		34	56	1527	1	S	C	
2	260		30	50	1527	1			
3	261		54	46	1528	2		C	
4	262		28.5	7.5	1513	1		C	
5	263		32.5	36	1538	1	C	P	
6	264		33	38	1499	1	C		
7	265		2	76	1515	2			Target Fell
8	266		21	65	1511	1		P	
9	267		46.5	16	1516	2	C		
10	268		40.5	0	1497	1			
11	269		28	69	1517	1			
12	270		79	49.5	1522	1		C	
13	271		64	43.5	1515	1	S		
14	272		66	49	1521	1			
15	273		30	51	1529	1	C	P	
16	274		107	71	1528	1			
17	275		53	39	1512	2	C	C	
18	276	1600	27	55.5	1531	1		C	

REMARKS

1. The total elevation of the tube throughout the test was 28 mils.
2. On test sample round number 7, the left target upright was hit causing the target to fall. The target was re-erected and the test continued.
3. The "C" under positioning ring condition and liner condition indicates that the particular liner or ring was cracked. The "S" under positioning ring condition indicates a shattered ring and the "P" under liner condition indicates a peeling liner which was exposing the case perforations.
4. All impact measurements were made from the bottom and left side of the target. The gun was boresighted on the left top corner of the 12' X 12' target.

13

FIRING RECORD NO: P 58702
SHEET 5 OF

ACCURACY TEST, T184E13, 1508 YARD RANGE

WIND VELOCITY: CALM
WIND DIRECTION: -
TEMPERATURE: -10°F

DATE: 17 February 1954
FIRING POSITION: D
DIRECTION OF FIRE: 310°
BORESIGHT ELEVATION: 1.6 MILS

TEST SAMPLE NO.	TUBE ROUND NO.	TIME OF FIRING	IMPACT LAT FT	COORDI- NATES VERT FT	MUZZLE AF- TER BURN- ING ING LOTH FT	POSITION- ING CONDI- TION	LINER CONDI- TION	MUZZLE VELOCITY FTS	TOTAL ELEVATION MILS
C/R 277	277	1510	Left	Low	1			1509	46
C/R 278	278		Left		1		C	1540	48
C/R 279	279		Left		2			1533	48
C/R 280	280		Left	Low	1	C	C	1530	48
C/R 281	281		Miss		1			1521	47
1	282	10.9	7.3	12		S		1536	48
2	283	12.4	4.4	1			C	1526	48
3	284	14.7	6.1	2			P	1526	48
4	285	7.9	13.55	1		C		1517	48
5	286	10.4	10.4	1		C	C	1526	48
6	287	5.9	9	1				1523	48
7	288	10.1	11.3	1		S	C	1522	48
8	289	6.1	14.65	1				1514	48
9	290		Low	2		C		1497	48
10	291	6.9	16.9	1				1510	48
11	292	6.75	13.65	1		C		1511	48
12	293	6.3	11.5	1		C		1515	48
13	294	9.6	14.45	1		C		1509	48
14	295	8.4	14.6	1				1512	48
15	296	1545	11.7	16.2	1		C	1500	48

REMARKS

1. The "C" under liner condition and positioning ring condition indicates that the particular liner or ring was cracked. The "S" under positioning ring condition indicates a shattered ring and the "P" under liner condition indicates a peeling liner which was exposing the case perforations.

2. All impact measurements were made from the top and left of the 18 foot high by 20 foot wide cloth target.

3. The gun was boresighted at the top left corner of the target.

24

ACCURACY TEST, T119E12, 1508 YARD RANGE

FIRING RECORD NO: P 58702
SHEET 6 OFWIND VELOCITY: 8 MPH
WIND DIRECTION: SW
TEMPERATURE: -12°FDATE: 22 February 1954
FIRING POSITION: D
DIRECTION OF FIRE: 310°
BORESIGHT ELEVATION: 1.6 MILS

TEST SAMPLE NO	TUBE ROUND NO	TIME OF FIRING	IMPACT COORDI- LAT FT NATES VERT FT	MUZZLE VELOCITY FPS	TOTAL ELEVATION MILS	REMARKS
C/R C/R C/R C/R	297 298 299 300			1546 1553 1545 1530	48 48 50 52	Missed target Missed target Missed target Missed target
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16	301 302 303 304 305 306 307 308 309 310 311 312 313 314 315 316	1050 301 302 303 304 305 306 307 308 1415 310 311 312 313 314 315 1430	4.2 5.4 3.5 6.9 9.3 0 5.8 High 2.1 3.9 High High High High High High	1557 1540 1538 1558 1534 1562 1536 1517 1564 1575 1554 1541 1558 1563 1548 1533	52 52 52 52 52 52 52 52 52 52 52 52 52 52 52 52	Missed target Missed target Missed target Missed target Hit upright, target fell

REMARKS

1. All impact measurements were made from the left and top of the 18 foot high by 20 foot wide cloth target.
2. Test sample round six hit one of the target supports causing the target to fall.

25

FIRING RECORD NO: P 58702
SHEET 7 OF

SUMMARY

T119E12	T119E12	T184E13	T184E13
1008 Yd Range	1508 Yd Range	1008 Yd Range	1508 Yd Range

Number of rounds fired in accuracy pattern not including conditioning rounds

16 16 18 15

Number of rounds which missed target in accuracy pattern not including conditioning rounds

0 3 0 1

Probable Error

Vertical (MILS) .333 .456 .387 .573
Lateral (MILS) .257 .305 .453 .401

Average Velocity (FPS)

- 1548 1519 1516

Maximum velocity dispersion
between rounds (FPS)

= 37 41 39

APPROVED BY:

A. B. DUKE
LT COL, ORD CORPS
Chief, Climatic Test Division
Development & Proof Services

Dr. E. Engelhardt

R. E. ENGELHARDT
PROJECT ENGINEER

26

CONFIDENTIAL

APPENDIX D

DATA REDUCTION ANALYSIS

21

CONFIDENTIAL

~~CONFIDENTIAL~~

HMaisel/mkh/21134

SUBJECT: Cold Weather Accuracy Comparison of Firings of the T184 Type and T119 Type Projectiles

1. At the request of Mr. Englehardt of the Southwest Institute, the Analytical Section has made an analysis of the cold weather accuracy firings described in firing records P-58702 and P-58703. These firings were conducted at Fort Churchill, Canada, during the period 13-24 Feb 54. The results obtained are summarized in Table I.

2. These results do not conclusively establish which projectile is more accurate because too few rounds were fired and because of the loss of information due to technical difficulties encountered during these firings (See footnotes to Table I for a description of these difficulties). The accuracy results do suggest the possible superiority of the T119 type projectile; but this conclusion cannot be accepted unless it is verified by further firings. It should be noted that the misses occurring at the 1500 yard range with the T184E12 and the T119E12 projectiles were ascribed to adverse test conditions rather than poor accuracy of the projectiles.

3. A number of the T184 rounds fired for accuracy had cracked or shattered positioning rings. Probable errors were calculated including only those T184 rounds having damaged positioning rings and also only for those T184 rounds with undamaged rings. It was found that the T184E13 rounds having damaged rings gave better accuracy than those rounds with undamaged rings. No conclusion regarding the effect of damaged rings on accuracy firings with the 106mm Rifle can be made since only four T184E12 rounds fired at the 1008 yard range and one T184E12 round fired at the 1508 yard range had damaged positioning rings. However, the results with the T184E13 rounds are sufficient to indicate that if the T184 type projectile does have poorer accuracy than the T119 type, this difference might not be related to the condition of the positioning rings.

4. Combined effects, such as that of rifle and projectile or date of firing and projectile, could not be determined because of the small number of rounds fired per target and the variation from target to target in the size of the accuracy group.

3 Incls.

1. Two (2) Tables
2. Two (2) Charts
3. Two (2) Firing Records

J. E. STEEDMAN

Propellant & Target Accuracy Unit
Arms and Ammunition Division

~~CONFIDENTIAL~~

11

TABLE I
Vertical Target Accuracy Results

Rifle	Range (yds)	Projectile	Date Fired	No. Rds. Pired		No. Rds. Missing Target	Probable Error(mils)
				Vertical	Lateral		
106mm T17031	1008	T119311	23 Feb 54	10	0	.37	.35
		T184312	24 Feb 54	17	2a	.49	.30
1508	1008	T119311	23 Feb 54	11	1	.30d	.24d
		T184312	23 Feb 54	16	4b	.39	.41
105mm M27	1008	T119312	13 Feb 54	16	0	.33	.26
		T184313	14 Feb 54	18	0	.39	.45
1508	1008	T119312	22 Feb 54	16	7c	.61	.40
		T184313	17 Feb 54	15	1	.57	.40

- a. Center of Impact of those rounds hitting the target was 42.2" from the left edge and 51.4" from the bottom of the target. One of the misses was noted as low.
- b. There appeared to be a shift in elevation after Rd. 6. The Center of Impact of those rounds hitting the target was 47.9" from the bottom of the target. The Center of Impact of the first six rounds was 62.6" from the bottom of the target. All four rounds that missed were short and were among the last ten rounds fired. The Center of Impact of the remaining six of the last ten rounds fired was 33.2" from the bottom of the target. However, the Vertical P. Z. of the first six rounds alone is .49 mils.
- c. The target fell after the sixth round was fired and after it was erected again, seven of the last ten rounds fired went over the target. The Vertical Center of Impact of the three rounds hitting the target was 37.2" from the top of the target.
- d. P. I.'s include one round which misfired initially and fired on the second attempt. Omitting this round, the Lateral P. I. is .12 mils.

Anal Sect, A&A Div, DAPS
2 Dec 54 HM

TABLE II
Probable Errors of Impacts of Rounds with Damaged and of Rounds with Undamaged Positioning Rings

<u>Rifle</u>	<u>Projectile</u>	<u>Range (Yds.)</u>	<u>Condition of Positioning Rings</u>	<u>Probable Error (mils)</u>		
				<u>No. Rds.</u>	<u>Vertical</u>	<u>Lateral</u>
105mm	T184 313	1008	Damaged	7	.24	.24
			Undamaged	11	.46	.56
105mm	T184 313	1508	Damaged	8	.41	.29
			Undamaged	6	.77	.55
106mm	T184 312	1008	Damaged	4	.65 (.14)*	.32
			Undamaged	11	.45	.31

* P. 3. omitting 1 round.


Anal Sect, A&A Div, D&PS
2 Dec 54 HM

VERTICAL TARGET ACCURACY OF CARTRIDGES HEAT T119E12 & T184E13
FIRED IN THE 105MM RIFLE M27, NO. 80

HEAT, T119E12


RANGE: 1008 YDS

DATE OF FIRING: 13 FEB 54



RANGE: 1508 YDS


DATE OF FIRING: 22 FEB 54



HEAT, T184E13


RANGE: 1008 YDS

DATE OF FIRING: 14 FEB 54



RANGE: 1508 YDS

DATE OF FIRING: 17 FEB 54



Probable errors were computed omitting seven rounds that missed the target (see attached Table I, footnote 1)

* THESE ROUNDS HAD DAMAGED POSITIONING RINGS


Lateral Deflections in Feet

Probable errors were computed omitting one round that missed the target
Anal Sect, AAA Div, D&PS
17 Nov 54 JRS

VERTICAL TARGET ACCURACY OF CARTRIDGES HEAT T119E11 & T184E12
FIRED IN THE 106MM RIFLE T170E1, NO. 8


HEAT, T119E11

Range: 1008 yds
Date of Firing: 23 Feb 54



Vertical P.E.: .37 mils
Lateral P.E.: .35 mils

Range: 1508 yds
Date of Firing: 23 Feb 54




Vertical P.E.: .39 mils
Lateral P.E.: .21 mils
Lateral P.E.: .12 mils (omitting *)

Probable errors were computed omitting one round that missed the target.

* THESE ROUNDS HAD DAMAGED POSITIONING RINGS.

HEAT, T184E12


Range: 1008 yds
Date of Firing: 24 Feb 54



Vertical P.E.: .49 mils
Lateral P.E.: .30 mils

Probable errors were computed omitting two rounds that missed the target (see attached Table I, footnote A)

Range: 1508 yds
Date of Firing: 23 Feb 54



Vertical P.E.: .39 mils
Lateral P.E.: .41 mils

Probable errors were computed omitting four rounds that missed the target (see attached Table I, footnote B)

Lateral Deflection in Feet

Anal Sect. A&A Div. B&PS
1 Dec 54 JES

CONFIDENTIAL

APPENDIX E
WEATHER DATA

43

CONFIDENTIAL

WEATHER DATA

All rounds were stored in an exposed location in fiber containers and packed two to a wooden crate.

The date of arrival at Fort Churchill of the T184E13 round was 13 February and 9 February for the T119E12 round. The following table indicates the daily temperature extremes to which the rounds were subjected.

DATE FEBRUARY	MAXIMUM RELATIVE HUMIDITY PERCENT	MAXIMUM TEMPERATURE DEGREES F	MINIMUM TEMPERATURE
			DEGREES F
9	95	2	-14
10	78	-13	-23
11	70	-13	-21
12	78	-8	-22
13	58	-22	-32
14	65	-19	-29
15	72	-23	-37
16	77	-10	-29
17	86	-8	-21
18	78	-5	-13
19	83	0	-13
20	90	-3	-25
21	95	-16	-26
22	75	-2	-24
23	87	4	-5
24	95	2	-16
25	95	1	-21

34

RECORD OF EQUIPMENT PERFORMANCE

Source for Rating - 143rd Report on Project TB5-1401

Item of Equipment: Shell, HEAT, 105mm, T18LE13Rated by: R. E. Engelhardt Date: 25 May 1954

	RATING	SOURCE	REMARKS
Durability			
<u>ENVIRONMENTAL FACTOR</u>			
Hard Surface Road			
Gravel Surface Road			
Unsurfaced Trail			
Rough Hard Ground			
Stony or Rocky Ground			
Sand (dry)			
Loose Sand (shallow water)			
Clay (wet)			
Muskeg (frozen)			
Muskeg (unfrozen)			
Frozen Ground			
Hilly or Mountainous			
Swamp			
Smooth Ice			
Rough Ice			
Pack Ice			
Hard Packed Snow			
Dry Snow, Powdery to 18"			
Dry Snow, Powdery over 18"			
Dry Snow, Compacted to 18"			
Dry Snow, Compacted over 18"			
Wet Snow			
Water less than 2' depth			
Water to 5' depth			
Water over 5' depth			
Temp. below -65°F. (storage)			
Temp. from -65°F. to -25°F.			
Temp. from -25°F. to +32°F.	1		Accuracy Satisfactory at 1000 and 1500
Temp. from +32°F. to +90°F.			Yard Ranges
Temp. from +90°F. to +125°F.			
Temp. over +125°F.			
Radiation, to 360 BTU/Ft.Sq./Hr.			
Dust, Airborne			
Blowing Sand			
Blowing Snow			
Rain			
Snowfall, Heavy			
Ice Fog			
Sleet (freezing)			
Wind (over 25 mph)			
Altitude to 5,000'			
Altitude over 5,000'			
Tropical Humidity			
Forest (open)			
Brush (dense)			
Tundra (unfrozen)			
Windchill (700 to 1400)			
Windchill (1400 to 1900)			
Windchill (over 1900)			

A

RECORD OF EQUIPMENT PERFORMANCE

Source of Rating - 143rd Report on Project TB5-1401

Item of Equipment: Shell, HEAT, 105mm, T119E12

Rated by: R. E. Engelhardt Date: 25 May 1954

	RATING	SOURCE	REMARKS
Durability			
ENVIRONMENTAL FACTOR			
Hard Surface Road			
Gravel Surface Road			
Unsurfaced Trail			
Rough Hard Ground			
Stony or Rocky Ground			
Sand (dry)			
Loose Sand (shallow water)			
Clay (wet)			
Muskeg (frozen)			
Muskeg (unfrozen)			
Frozen Ground			
Hilly or Mountainous			
Swamp			
Smooth Ice			
Rough Ice			
Pack Ice			
Hard Packed Snow			
Dry Snow, Powdery to 18"			
Dry Snow, Powdery over 18"			
Dry Snow, Compacted to 18"			
Dry Snow, Compacted over 18"			
Wet Snow			
Water less than 2' depth			
Water to 5' depth			
Water over 5' depth			
Temp. below -65°F. (storage)			
Temp. from -65°F. to -25°F.			
Temp. from -25°F. to +32°F.	1	1	Accuracy Satisfactory at 1,000 Yards
Temp. from +32°F. to +90°F.			
Temp. from +90°F. to +125°F.			
Temp. over +125°F.			
Radiation, to 360 BTU/Ft.Sq./Hr.			
Dust, Airborne			
Blowing Sand			
Blowing Snow			
Rain			
Snowfall, Heavy			
Ice Fog			
Sleet (freezing)			
Wind (over 25 mph)			
Altitude to 5,000'			
Altitude over 5,000'			
Tropical Humidity			
Forest (open)			
Brush (dense)			
Tundra (unfrozen)			
Windchill (700 to 1400)			
Windchill (1400 to 1900)			
Windchill (over 1900)			

B

CONFIDENTIAL

APPENDIX G

PHOTOGRAPH

36

CONFIDENTIAL



196304

ABERDEEN PROVING GROUND

10 February 1954

WINTER TEST 1953-54, FORT CHURCHILL, MANITOBA, CANADA
Project No. TB5-1401/143. Winter Test, 1953-54. Comparing Cartridges
T119E12 and T184E13. A comparison of arctic and conventional gloves
while using the firing handle of the 105mm Recoilless Rifle, M27.



A96305

8 ABERDEEN PROVING GROUND 8

10 February 1954

WINTER TEST 1953-54, FORT CHURCHILL, MANITOBA, CANADA
Project No. TB5-1401/143. Winter Test, 1953-54. Comparing Cartridges
T119E12 and T184E13. Recoilless Rifle, 105mm, M27, mounted on 1/4-Ton
Truck, emplaced at firing position.



8 ABERDEEN PROVING GROUND 8

496306

10 February 1954

WINTER TEST 1953-54, FORT CHURCHILL, MANITOBA, CANADA
Project No. TB5-1401/143. Winter Test 1953-54. Comparing Cartridge
T119E12 and T184E13. Damage to T184 type Cartridge support ring
incurred during shipment and handling.

CONFIDENTIAL

AN07757

Armed Services Technical Information Agency

Reproduced by
DOCUMENT SERVICE CENTER
KNOTT BUILDING, DAYTON, 2, OHIO

This document is the property of the United States Government. It is furnished for the duration of the contract and shall be returned when no longer required, or upon recall by ASTIA to the following address: **Armed Services Technical Information Agency, Document Service Center, Knott Building, Dayton 2, Ohio.**

NOTICE: WHEN GOVERNMENT OR OTHER DRAWINGS, SPECIFICATIONS OR OTHER DATA ARE USED FOR ANY PURPOSE OTHER THAN IN CONNECTION WITH A DEFINITELY RELATED GOVERNMENT PROCUREMENT OPERATION, THE U. S. GOVERNMENT THEREBY INCURS NO RESPONSIBILITY, NOR ANY OBLIGATION WHATSOEVER; AND THE FACT THAT THE GOVERNMENT MAY HAVE FORMULATED, FURNISHED, OR IN ANY WAY SUPPLIED THE SAID DRAWINGS, SPECIFICATIONS, OR OTHER DATA IS NOT TO BE REGARDED BY IMPLICATION OR OTHERWISE AS IN ANY MANNER LICENSING THE HOLDER OR ANY OTHER PERSON OR CORPORATION, OR CONVEYING ANY RIGHTS OR PERMISSION TO MANUFACTURE, USE OR SELL ANY PATENTED INVENTION THAT MAY IN ANY WAY BE RELATED THERETO.

CONFIDENTIAL